



09/903161

Cofe

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of

U.S. Patent No. : 6,944,694 B2
Issued : September 13, 2005
Title : ROUTABILITY FOR MEMORY DEVICES
Docket No. : MIO 0076 PA/40509.145

Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on May 12, 2006.

Kristina E. Swanson
Kristina E. Swanson - Attorney

Reg. No. 53,657

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE
UNDER 35 U.S.C. 254 and 37 C.F.R. 1.322

In the matter of U.S. Patent No. 6,944,694 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

- Col. 1, line 9 "unil" should read --unit--;
- Col. 1, line 46 "constrcted" should read --constructed--;
- Col. 3, line 28 "AItematively," should read --Alternatively--;
- Col. 4, line 3 "1048" should read --104B--;
- Col. 4, line 10 "10" should read --110--;
- Col. 4, line 54 "information" should read --information--;
- Col. 5, line 67 "206," should read --206--;
- Col. 7, line 66 "mnemory" should read --memory--;
- Col. 13, line 16 "arrangements;" should read --arrangement--;
- Col. 13, line 21 "processors," should read --processor--;
- Col. 13, line 34 "and" should read --said--;
- Col. 13, line 45 "a" should be deleted;
- Col. 13, line 62 "arrangement;" should read --assignment--;
- Col. 14, line 30 "arranging" should read --rearranging--;

Certificate
MAY 17 2006
of Correction

MAY 18 2006

Col. 14, line 61 "position" should read --positions--;
Col. 17, line 45 "address" should read --address bus--;
Col. 19, line 52 "multiplexers" should read --multiplexer--;
Col. 20, line 38 "inputs," should read --input,--;
Col. 21, line 12 "bank;" should read --banks--;
Col. 21, line 59 "p1" should be deleted.

REMARKS

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. Two (2) copies of the required Certificate of Correction Form PTO/SB/44 are enclosed.

Respectfully submitted,
DINSMORE & SHOHL LLP

By Kristina E. Swanson
Kristina E. Swanson
Registration No. 53,567

One Dayton Centre
One South Main St., Suite 1300
Dayton, Ohio 45402-2023
Telephone: (937) 449-6400
Facsimile: (937) 449-6405

KES/bab
Encl.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,944,694 B2

APPLICATION NO.: 09/903,161

ISSUE DATE : September 13, 2005

INVENTOR(S) : Pax

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 1, line 9 "unil" should read --unit--;
Col. 1, line 46 "constrcted" should read --constructed--;
Col. 3, line 28 "AJtematively," should read --Alternatively--;
Col. 4, line 3 "1048" should read --104B--;
Col. 4, line 10 "10" should read --110--;
Col. 4, line 54 "information" should read --information--;
Col. 5, line 67 "206," should read --206--;
Col. 7, line 66 "mnemory" should read --memory--;
Col. 13, line 16 "arrangements;" should read --arrangement--;
Col. 13, line 21 "processors," should read --processor--;
Col. 13, line 34 "and" should read --said--;
Col. 13, line 45 "a" should be deleted;
Col. 13, line 62 "arrangement;" should read --assignment--;
Col. 14, line 30 "arranging" should read --rearranging--;
Col. 14, line 61 "position" should read --positions--;
Col. 17, line 45 "address" should read --address bus--;
Col. 19, line 52 "multiplexers" should read --multiplexer--;
Col. 20, line 38 "inputs," should read --input--;
Col. 21, line 12 "bank;" should read --banks--;
Col. 21, line 59 "p1" should be deleted.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Dinsmore & Shohl, LLP
One Dayton Centre
One South Main Street, Suite 1300
Dayton, Ohio 45402

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

MAY 18 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,944,694 B2
APPLICATION NO.: 09/903,161
ISSUE DATE : September 13, 2005
INVENTOR(S) : Pax

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 1, line 9 "unil" should read --unit--;
Col. 1, line 46 "constrcted" should read --constructed--;
Col. 3, line 28 "AJtematively," should read --Alternatively--;
Col. 4, line 3 "1048" should read --104B--;
Col. 4, line 10 "10" should read --110--;
Col. 4, line 54 "information" should read --information--;
Col. 5, line 67 "206," should read --206.--;
Col. 7, line 66 "mnemory" should read --memory--;
Col. 13, line 16 "arrangements;" should read --arrangement--;
Col. 13, line 21 "processors," should read --processor--;
Col. 13, line 34 "and" should read --said--;
Col. 13, line 45 "a" should be deleted;
Col. 13, line 62 "arrangement;" should read --assignment--;
Col. 14, line 30 "arranging" should read --rearranging--;
Col. 14, line 61 "position" should read --positions--;
Col. 17, line 45 "address" should read --address bus--;
Col. 19, line 52 "multiplexers" should read --multiplexer--;
Col. 20, line 38 "inputs," should read --input--;
Col. 21, line 12 "bank;" should read --banks--;
Col. 21, line 59 "p1" should be deleted.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Dinsmore & Shohl, LLP
One Dayton Centre
One South Main Street, Suite 1300
Dayton, Ohio 45402

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

MAY 18 2006